

THE FRASER DIFFERENCE

2017 BOND

Proposed improvements at Salk Elementary are:

- Replace failing roof, which is out of warranty and leaking.
- Add a parking lane along the east side of the parking lot to ease traffic.
- Resurface parking lot which is cracked and crumbling.
- Install underground storm water drainage. The current system allows for water and ice to build up on sidewalks and play areas.
- Update classroom technology, student devices, and technology infrastructure when it reaches the end of its useful life.
- Add flexible furniture to classrooms to allow for collaboration, small groups and personalized learning.
- Replace classroom coat cubbies, many of which are original to the buildings and are broken, missing or falling apart.
- Replace classroom cabinets, which are starting to break down from use and exposure to water.
- Add air conditioning to gymnasium and kitchen. These spaces are used for assemblies, lunches and classes.
- Install a sound-absorbing gymnasium ceiling and add a sound system to the gym.
- Improve playground equipment and resurface asphalt play areas.



**Vote
May 2**

